

HCC Fault Reports

DATE	LOCATION	FAULT REPORT NO	DETAILS	COMMENTS FROM HCC	STATUS
11.07.2025	FP31	401004711020	Dangerous to walk due to scrap metal, old fencing and machinery buried and making the footpath unstable	With ROW Team	ONGOING
19.07.2025	Crossroads at Mentley Lane and Munden Road What3Words location ///clock.airbase.pheasants,	401004719613	The crossroads lines have faded to be almost non existent. A recent accident highlighted that the crossroads highlighted that it is now becoming dangerous as cars do not know they have to stop/giveway when approaching Great Munden from Mentley Lane. Signage would also be useful to prevent future accidents too but road markings are now essential and urgent.	Fault report 401004719613 has now been added to 2025 Road Marking Programme – date tbc.	ONGOING
15.08.2025	Location: Crossroads at Mentley Lane and Munden Road What3Words location ///clock.airbase.pheasants , Mentley Lane West, Standon	401004750985	Great Munden Parish Council have already reported under case no 401004719613 In the past 7 years there have been 5 vehicle accidents. There are 3 issues at the junction. 1. The white line road markings have faded and drivers cannot see clearly that there is a crossroads 2. The position of the faded existing lines are in the wrong position for safety. If the left hand lane approaching the crossroads from the A10 was moved to the left with the white triangle moved 3-4 ft to the left, then vehicles would be directed to swing over to the left of the road thus gaining a clearer vision of traffic on the Great Munden Road.	The reference number is: 401004750985 Fault type: ROAD AND CYCLE LANE Location: Mentley Lane West, Standon Thanks for telling us about this issue. Based on the information you provided, we have assessed this fault and it doesn't need attention right now as it doesn't yet meet our criteria for repair.	Referred to Terry Smith Sept 2025